



The New Piper Aircraft, Inc.
2926 Piper Drive
Vero Beach, Florida, U.S.A. 32960

SERVICE *No. 1043* LETTER

Date: April 25, 2002 (S)

SUBJECT:

OIL COOLER KIT

MODELS AFFECTED:

PA-32R-301T Saratoga

SERIAL NUMBERS AFFECTED:

3257001 through 3257272

COMPLIANCE TIME:

At the next regularly scheduled maintenance event or at the discretion of the operator.

APPROVAL:

The alteration as specified in the instructions section has been shown to comply with the applicable Federal Aviation Regulations and is FAA approved.

PURPOSE:

This Service Letter announces the availability of a new oil cooler that improves 'Cold Weather Operation'. The new design eliminates the need for installation of the 'winterization plates' when ground or in-flight temperatures are expected to be below 15°F.

INSTRUCTIONS:

1. Incorporate the Oil Cooler Kit, Piper part number 767-332, on the aircraft.
2. Make a logbook entry indicating compliance with this Service Letter.

(OVER)

ATA: 7921

MATERIAL REQUIRED: One (1) each, Oil Cooler Kit, Piper part number 767-332, per aircraft

AVAILABILITY OF PARTS: Your Piper Field Service Facility.

EFFECTIVITY DATE: This Service Letter is effective upon receipt.

SUMMARY: Applicable Factory Participation is limited to new aircraft in warranty at the time of compliance. Factory Participation will remain in effect for a period of time **not to exceed 180 days** from the date of this Service Letter.

Please contact your Factory Authorized Piper Service Facility to make arrangements for compliance with this Service Letter in accordance with the compliance time indicated.

NOTE: If you are no longer in possession of this aircraft, please forward this information to the present owner/operator and notify the factory of address/ownership corrections. Changes should include aircraft model, serial number, current owner's name and address.

Corrections/changes should be directed to:

THE NEW PIPER AIRCRAFT, INC.
Attn: Customer Care
2926 Piper Drive
Vero Beach, FL 32960